

S/N	Name of ship	Incident Type	Date of incident	Time of incident	Flag of ship	Type of ship	Latitude	Longitude	Area location	Area description	Ship activity	Attack method & description of incident	CAT
1.	<i>Asia Graeca</i>	Robbery / Theft	18 Sep 2021	0245	CYPRUS	BULK CARRIER	1° 17.2' N	104° 19.9' E	Straits of Malacca & Singapore	Approximately 5.8 nm north of Tanjung Pergam, Bintan Island, (Indonesia), in the eastbound lane of the Traffic Separation Scheme (TSS) in the Singapore Strait	While Sailing	While underway, five perpetrators armed with gun and knives were sighted in the vicinity of the engine room. There was no confrontation between the crew and the perpetrators . The alarm was raised and search onboard the ship was conducted. At 0638 hrs, the master updated Singapore Vessel Traffic Information System (VTIS) that the search was completed with no further sighting of the perpetrators. Nothing was reported stolen . A safety navigational broadcast was initiated. The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard were notified. Information of the incident was shared with the Malaysian and Indonesian authorities.	2
2.	<i>Delphinus</i>	Robbery / Theft	17 Sep 2021	2250	SINGAPORE	BULK CARRIER	1° 16.92' N	104° 19' E	Straits of Malacca & Singapore	Approximately 6 nm of Tanjung Pergam, Bintan Island, (Indonesia), in the eastbound lane in the Singapore Strait	While Sailing	While underway, the second engineer and fourth engineer spotted three perpetrators in the boiler area adjacent to the steering gear room exit door. The perpetrators fled towards the poop deck upon being discovered. The master activated the alarm and mustered all crew at the bridge. He turned on all of the deck lights and conducted a thorough search of the ship. The perpetrators were not found. The master reported the incident to the coastal state. The crew was not injured and nothing was stolen.	4
3.	<i>Athenia</i>	Robbery / Theft	13 Sep 2021	0415	SINGAPORE	PETROLEUM /CHEMICAL TANKER	1° 15' N	103° 23' E	Straits of Malacca & Singapore	Johor VTS Sector 6 in the Malacca Strait	While Sailing	While underway, an engine oiler spotted four perpetrators entering the engine room. The perpetrators escaped upon being discovered. The general alarm was raised and deck lights turned on. The incident was reported to the bridge and an announcement was made to alert all crew. A search was conducted by the crew and there was no further sighting of the perpetrators. Nothing was reported missing. The crew was not injured and there was no reported damage to the ship.	4