

Incident Report : 05/2015

Name and Type of Ship : *Orkim Harmony* / product tanker

Date/Time of Last Known Position : 11 Jun 15 at about 2054 hrs (local time)

Location of Last Known Position : 02° 08.90' N, 104° 27.30' E

Area Description : Approximately 17 nm southwest of Pulau Aur, Malaysia

Detail of Incident

1. The ReCAAP ISC received information that the shipping company of Malaysia-registered product tanker, *Orkim Harmony* had reported loss of communications with the vessel. The company had been receiving the vessel's hourly position update until 11 Jun 15 at about 2054 hrs. Subsequently, attempts to contact the vessel on all available communications were not successful. The ship's last known position was at 02° 08.90' N 104° 27.30' E (17 nm southwest of Pulau Aur, Malaysia).



Orkim Harmony
(photo courtesy of shipping company)


2. The Malaysian Maritime Enforcement Agency (MMEA) and the Indonesian Navy has reportedly deployed patrol boats to search for *Orkim Harmony*. *Orkim Harmony* is carrying 6,000 metric tonnes of ULG 95 (petrol) and has crew comprising Indonesians, Malaysians and Myanmar nationals onboard.

Reported by: Information Fusion Centre (IFC)

Comments

3. The ReCAAP ISC requests all vessels to look out for *Orkim Harmony* and to report sighting of the vessel to the nearest coastal State.

4. Coincidentally, *Orkim Harmony's* sister vessel, *Orkim Victory* was siphoned off 770 metric tonnes of Automotive Diesel Oil (ADO) on 4 Jun 15 in the vicinity, approximately 15.2 nm southwest of Pulau Aur. See map below on the approximate locations. Ship masters and crew are advised to exercise enhanced vigilance when transiting the area.



Approximate location of last known position of *Orkim Harmony* and location of siphoning of ADO from sister vessel, *Orkim Victory* on 4 Jun 15